				T #3
L Number	Hits	Search Text	DB	Time stamp
1	17	"0197486"	EPO;	2003/11/25
2	0	"0197486"	DERWENT EPO	13:59 2003/11/25
ı				13:58
3	0	"197486"	EPO	2003/11/25
4	0	"catalyst regeneration process and	EPO;	2003/11/25
5	0	apparatus" "ep-0197486-A1"	DERWENT EPO;	13:59 2003/11/25
	<u> </u>	•	DERWENT	14:02
6	1	("3394076").PN.	USPAT	2003/11/25
7	11	3394076.URPN.	USPAT	2003/11/25 14:02
8	1575850	slot slots opening openings slit slits hole holes	USPAT	2003/11/25 14:12
9	75864	slotted	USPAT	2003/11/25 14:12
10	2191072	plurality several multiple	USPAT	2003/11/25 14:12
11	218161	(slot slots opening openings slit slits hole holes) near3 (plurality several multiple)	USPAT	2003/11/25 14:13
12	260520	standpipe pipe	USPAT	2003/11/25 14:13
13	5458	(slotted or ((slot slots opening openings slit slits hole holes) near3 (plurality	USPAT	2003/11/25 14:13
14	57830	several multiple))) with (standpipe pipe) FCC regenerator regeneration	USPAT	 2003/11/25 14:14
15	131	((slotted or ((slot slots opening openings slit slits hole holes) near3 (plurality several multiple))) with (standpipe pipe)) and (FCC regenerator	USPAT	2003/11/25 14:14
16	233707	regeneration) catalyst	USPAT	2003/11/25
17	2681	(standpipe pipe) near5 catalyst	USPAT	14:14 2003/11/25 14:14
18	37	<pre>(((slotted or ((slot slots opening openings slit slits hole holes) near3 (plurality several multiple))) with (standpipe pipe)) and (FCC regenerator regeneration)) and ((standpipe pipe) near5 catalyst)</pre>	USPAT	2003/11/25
19	14	"32344770" "2391327" "3161583" "3206393" "3316170" "4217243" "4217244" "4243517" "4243518" "4354957" "4374021" "4440725" "4849091" "4965232").PN.	USPAT	2003/11/25 14:17
20	8	("3494858" "3661800" "3886060" "3893812" "3898050" "3909392"	USPAT	2003/11/25 14:21
21	19	"3926778" "3926843").PN. 3494858.URPN.	USPAT	2003/11/25
-	1	("6228328").PN.	USPAT	2003/10/30 16:02
-	16	("2530243" "2581134" "2741546" "2769771" "2893851" "2944009" "3031769" "3099538" "3394076" "3607730" "3775302" "4329526" "4511434" "5529587" "5562818" "5779746").PN.	USPAT	2003/10/30
	10139	FCC FCC	USPAT	2003/10/30
-	3752	standpipe	USPAT	2003/10/30
	683325	openings slots slits inlets	USPAT	2003/10/30

Search History 11/25/03 3:38:27 PM Page 1

	239	standpipe with (openings slots slits	USPAT	2003/10/30
_	2.59	inlets)		16:03
_	7	FCC and (standpipe with (openings slots	USPAT	2003/10/30
	,	slits inlets))		16:05
_	76515		USPAT	2003/10/30
	70313	Clacking		16:05
_	16	cracking and (standpipe with (openings	USPAT	2003/10/30
	1	(slots slits inlets))		16:05
	9	(cracking and (standpipe with (openings	USPAT	2003/10/30
	1	slots slits inlets))) not (FCC and		16:05
		(standpipe with (openings slots slits		
		inlets)))		
_	60724	outlets	USPAT	2003/10/30
		000000		16:11
	42	standpipe with outlets	USPAT	2003/10/30
	1		l	16:11
-	8	(standpipe with outlets) and (FCC or	USPAT	2003/10/30
		cracking)	ļ	16:14
_	10	("2654659" "2816011" "2881130"	USPAT	2003/10/30
		"2881133" "3016624" "3092468"		16:13
		"3215508" "4051013" "4101288"		
ı		"4226830").PN.		
· -	17389	riser	USPAT	2003/10/30
				16:14
-	706087	openings slots slits inlets outlets	USPAT	2003/10/30
				16:14
	1433	riser with (openings slots slits inlets	USPAT	2003/10/30
	}	outlets)		16:14
-	267	(riser with (openings slots slits inlets	USPAT	2003/10/30
	}	outlets)) and (FCC or cracking)		16:17
~	8595	regenerator	USPAT	2003/10/30
				16:17
-	183	((riser with (openings slots slits inlets	USPAT	2003/10/30
		outlets)) and (FCC or cracking)) and		16:17
		regenerator		0000/10/100
_	1	("3394076").PN.	USPAT	2003/10/30
				16:30
_	27		USPAT	2003/10/30
		"2434567" "2459474" "3041273"		16:35
]	"3152065" "3785959" "3835023"		Ì
	Į	"3849291" "3990992" "4026789"		1
	1	"4176084" "4200520" "4239654" "4242237" "4289606" "4331533"		1
	l	"4242237" "4289606" "4331533" "4332673" "4332674" "4336160"		
	1	"4332673" "4332674" 4336160		
	ţ	"4407714" "4427537" "4434049").PN.		(
	1	4401/14 4421001 4404049 EN-	1	